

Hydrim C61 G4 DC Power Source Removing & Reinstalling Part #01-113266S




Figure 24

Removing & reinstalling DC power source

Turn off unit and disconnect power cord.

Remove 7 wires connected to the DC power source.

Remove 1 screw at the front right of the power source bracket and loosen 1 screw at the back of the bracket.

Slide forward to remove.

To reinstall:

Slide the bracket back into position, tighten the rear screw and replace the screw at front right.

Reattach wires according to Figure 24.